

NIX, INC.

productronica
A2.134
ALTUS
SUPPORTING THE ELECTRONICS
United Kingdom
Ireland
www.altusgroup.com

Magazine Washer

Customer's Problems...

1. Difficult to remove contaminants on Magazines
2. Takes time to manually clean Magazines
3. Tough contaminants still remains after cleaning

Solutions

Easy removal contaminants on Magazines with "Micro bubbles"

Table 1

1. Contaminant	2. Cleaning	3. Rinse	4. Dry
----------------	-------------	----------	--------

Table 2

1. Contaminant	2. Cleaning	3. Rinse	4. Dry
----------------	-------------	----------	--------

Power Cyclone 3D

Customer's Problems...

1. Soldering defects due to PCB dust particles
2. Electrostatic discharge failure due to the contamination

Solutions

Patented solvent based Cleaner
Conductive brush (Rotary) + Chisel
Heat conductive + Laser

Table 1

1. Contaminant	2. Cleaning	3. Rinse	4. Dry
----------------	-------------	----------	--------

Table 2

1. Contaminant	2. Cleaning	3. Rinse	4. Dry
----------------	-------------	----------	--------

NIX PCB SOLUTION GUIDE

